



*Figure 1: Southeast-facing view of existing inground pool in rear yard.*



*Figure 2: Rear yard as seen from southeast corner of lot, facing west.*



*Figure 3: Existing drain in rear yard, located between pool and rear lot line.*



*Figure 4: East-facing view of existing drain, pool, and pool equipment in southern portion of rear yard.*



Figure 5: Existing pool equipment (to be moved), pool, and rear of dwelling, as seen from southeast corner of lot.



Figure 6: Existing pool equipment (to be moved) in southeast corner of lot.



*Figure 7: Existing concrete slab in southwest corner of lot, as seen from side yard facing south. Proposed to support future shed and relocated pool equipment.*