

Ministry of the Environment, Conservation and Parks - Inspection Summary Rating Record (Reporting Year - 2021-2022)

**DWS Name:** MUNICIPALITY OF LAKESHORE DRINKING WATER SYSTEM  
**DWS Number:** 260091507  
**DWS Owner:** MUNICIPALITY OF LAKESHORE  
**Municipal Location:** LAKESHORE

**Regulation:** O.REG. 170/03  
**DWS Category:** DW Municipal Residential  
**Type of Inspection:** Focused  
**Inspection Date:** Dec-6-2021  
**Ministry Office:** Windsor Area Office

**Maximum Risk Rating:** 578

Inspection Module	Non Compliance Rating
Source	0 / 0
Capacity Assessment	0 / 30
Treatment Processes	21 / 257
Operations Manuals	0 / 28
Logbooks	0 / 18
Certification and Training	0 / 42
Water Quality Monitoring	0 / 112
Reporting & Corrective Actions	0 / 91
<b>Overall - Calculated</b>	<b>21 / 578</b>

**Inspection Risk Rating:** 3.63%

**Final Inspection Rating:** 96.37%

Ministry of the Environment, Conservation and Parks - Detailed Inspection Rating Record (Reporting Year - 2021-2022)

**DWS Name:** MUNICIPALITY OF LAKESHORE DRINKING WATER SYSTEM  
**DWS Number:** 260091507  
**DWS Owner Name:** MUNICIPALITY OF LAKESHORE  
**Municipal Location:** LAKESHORE

**Regulation:** O.REG. 170/03  
**DWS Category:** DW Municipal Residential  
**Type of Inspection:** Focused  
**Inspection Date:** Dec-6-2021  
**Ministry Office:** Windsor Area Office

Non-Compliant Question(s)	Question Rating
<b>Treatment Processes</b>	
Were all parts of the drinking water system that came in contact with drinking water (added, modified, replaced or extended) disinfected in accordance with a procedure listed in Schedule B of the Drinking Water Works Permit?	21
<b>Overall - Total</b>	<b>21</b>

**Maximum Question Rating:** 578

**Inspection Risk Rating:** 3.63%

**FINAL INSPECTION RATING:** 96.37%